




1




2




3




4




5








6



7



① x1 	② x2 	③ x1 	④ x1 	⑤ x2 
⑥ x1 	⑦ x2 	⑧ x1 	⑨ x1 	⑩ x2 
⑪ x2 	⑫ x2 	⑬ x2 	Ax24 	Bx24 
Cx4  M6*40	Dx8  M6*35	Ex1  M6*10	Fx4  Parker screw 45MMX4	Gx16  Parker screw 14MMX16
Hx5 	Ix1 	Jx1 		